

## Futures Fire Risk Assessment

Futures Homescape, Apartments 67A-G  
Hallam Road: NG3 6HR, - UPRN: 15046 /  
173605 / QA Approved / Andy Cloke

**Complete**

<b>Flagged items</b>	2	<b>Actions</b>	8
----------------------	---	----------------	---

**SITE NAME:**

Futures Homescape, Apartments  
67A-G Hallam Road: NG3 6HR, -  
UPRN: 15046, Fire Risk  
Assessments, Futures Homescape

**PROPERTY IMAGE**



Photo 1

<b>UPRN:</b>	15046
<b>JOB NUMBER:</b>	173605
<b>FRA COMPLETED BY:</b>	Pennington Choices Limited
<b>FIRE RISK ASSESSOR NAME:</b>	Jamie Yarwood
<b>INSPECTION DATE:</b>	16 Jan 2024
<b>REPORT STATUS:</b>	QA Approved
<b>REASSESSMENT PRIORITY</b>	Medium - 2 Years
<b>VALID TO: (QA Use Only)</b>	28 Jan 2026
<b>VALIDATION DATE: (QA Use Only)</b>	28 Jan 2024
<b>VALIDATED BY: (QA Use Only)</b>	Andy Cloke

**VALIDATOR'S SIGNATURE: (QA Use Only)**



Photo 2

---

## Flagged items & Actions

2 flagged, 8 actions

### Flagged items

2 flagged, 0 actions

Assessment Risk Ratings / Premises Risk Rating

**Accordingly, it is considered that the risk to life from fire at these premises is:**

MODERATE

Assessment Risk Ratings

**On satisfactory completion of all remedial works the risk rating of this building may be reduced to**

TOLERABLE

### Other actions

8 actions

Detailed Risk Assessment Part 2 / B - Smoking Policies / B2

**Is the policy being adhered to and are "No smoking" signs provided in the common areas?**

Yes

No evidence of illicit smoking at time of assessment and no smoking signage was not provided in the common area.

**Open** | Priority: Medium | Due: 28 Apr 2024 7:58 PM BST | Created by: Jamie Yarwood

B2

Provide a no smoking sign on the wall of the open staircase at ground floor.

Detailed Risk Assessment Part 2 / F - Lightning / F1

**Does the building have a lightning protection system?**

No

No lightning protection on the building noted.

**Open** | Created by: Jamie Yarwood

F1

Recommend management undertake a risk assessment of the building to determine if lightning protection is required.

Detailed Risk Assessment Part 2 / G - Housekeeping / G2

**Are the escape routes kept clear of items combustible materials or waste and free of any trip hazards?**

No

Potted plants noted on the first floor open deck.



Photo 10

**Open** | Priority: Low | Due: 28 Jan 2025 8:03 PM GMT | Created by: Jamie Yarwood

G2

Potted plants as noted should be removed from the open deck and residents advised not to use the open deck for storage of personal items.

Detailed Risk Assessment Part 2 / L - Flat Entrance Doors / L1

**Are the sample inspection flat entrance door or doors in good condition and appropriately fire rated?**

Unknown

It was unable to be confirmed if flat entrance doors offer 30 minutes fire resistance. Ineffective flat entrance doors in a fire condition may allow smoke heat and fire to spread; this may impede escape and may cause physical harm to the occupants of the building. Flat F presents a passing risk.



Photo 13



Photo 14




Photo 15



Photo 16



Photo 17



Photo 18



Photo 19

**Open** | Priority: Medium | Due: 28 Apr 2024 8:27 PM BST | Created by: Jamie Yarwood

L1

Management to confirm that adequate FD30 certification is present for the flat entrance door as noted. If certification is unavailable, then a fire door survey should be undertaken to the flat entrance door by a competent 3rd party accredited company. Any recommendations from such a survey should be implemented as soon as practicable.

Detailed Risk Assessment Part 2 / P - Means of Giving Warning in Case of Fire / P7

**If applicable, is a separate domestic hard-wired smoke/heat alarm within the flats installed to a suitable standard?**

Unknown

No access to individual flats at time of inspection to check for hard wired smoke alarms.

**Open** | Priority: Medium | Due: 28 Apr 2024 8:31 PM BST | Created by: Jamie Yarwood

P7

It is recommended that each flat is checked to confirm that BS5839-6:2019 Grade D, LD2 detection is fitted.

Detailed Risk Assessment Part 2 / Q - Measures to Limit Fire Spread and Development / Q4

**Is compartmentation maintained in the roof space?**

Unknown

No access to any roof void above individual flats.

**Open** | Priority: Medium | Due: 28 Apr 2024 8:35 PM BST | Created by: Jamie Yarwood

Q4

Management to check the compartmentation between individual dwellings, any breaches in compartmentation are recommended to be rectified by a competent third party company.

Detailed Risk Assessment Part 2 / T - Procedures and Arrangements / T6

**Are there adequate procedures in place for the evacuation of disabled people who are likely to be present?**

Unknown

Unknown if suitable arrangements were in place for any persons within the premises with disabilities.

**Open** | Created by: Jamie Yarwood

T6

PEEPs are currently not applicable in general needs properties, however a Person-Centred Fire Risk Assessment (PCFRA) may be appropriate, if a resident has been identified as especially vulnerable and at risk from fire hazards in their property. It is recommended that the provider works with the identified vulnerable resident or their representative to help to reduce risk from fire and where necessary involve other agencies. In addition refer to Y1.

Detailed Risk Assessment Part 2 / Y - Engagement with Residents / Y1

**Has all Fire Safety information & procedures been disseminated to the residents?**

Unknown

No information available at the time of assessment.

**Open** | Created by: Jamie Yarwood

Y1

Management to confirm that information on fire procedures are shared with residents on sign-up of the property, with regular updates on their website, property notice boards, specific mailings etc.

## Detailed Risk Assessment Part 1

### 1. General Information

<b>1.1 FRA Type:</b>	Type 1
<b>1.2 Property Type:</b>	Purpose Built Block of Flats
<b>1.3 Property Designation:</b>	General Needs
<b>1.4 Responsible Person:</b>	Lindsey Williams - CEO Futures Housing Group
<b>1.5 No of Floors:</b>	2
<b>1.6 No of Flats (if applicable):</b>	7
<b>1.7 Ground Floor Area (m2):</b>	200
<b>1.8 Total Area of all Floors (m2)</b>	400

### 1.9 Building Description:

Two storey purpose built block utilised as general needs accommodation consisting of seven flats with four flats at ground floor, all accessed directly from outside (A,B,C,D) and three flats at first floor level (E,F,G) accessed from an open deck. There is a single staircase with open access at ground floor and there is no lift installed. There is a dedicated bin storage area to the rear of and sufficiently away from the building and there does not appear to be an electrical intake cupboard, however what appear to be electrical intake cabinets were noted on the open deck. The first floor of the building is provided with open access.




Photo 3




Photo 4



Photo 5

### 1.10 Building Construction:

Brick built building with concrete floors and staircase, the building is provided with a pitched timber roof over the dwellings (not over the open deck) and has a brick faced external fascia.



Photo 6



Photo 7




Photo 8

### 1.11 Extent of common areas:

Open deck, staircase, landing, escape routes internal and external.

### 1.12 Areas of the building to which access was not available:

Individual flats.

**1.13 If applicable, state which flats were sample inspected:**

None available at time of inspection.

**2. The Occupants**

**2.1 Management Extent**

Non Managed – eg GN

**2.2 Details of any onsite Management**

General needs building with no permanent onsite management, occasional visits by Futures staff and contractors expected.

**2.3 Person managing fire safety in the premises**

Lindsey Williams, Chief Executive, Futures Housing.

**2.4 Person consulted during the fire risk assessment**

No person consulted.

**2.5 Number of occupants (maximum estimated)**

14 estimated at two persons per flat.

**2.6 Approximate maximum number of employees at any one time**

Residential block with no onsite management, occasional visits by Futures staff and contractors expected.

**2.7 Number of members of the public (maximum estimated)**

Residential block, low numbers expected.

**2.8 Identify any people who are especially at risk (Sleeping Occupants, Disabled Occupants, Occupants in remote areas and Lone Workers, Young Persons, Others)**

This is a 'general needs' building. The premises will have sleeping occupants, and it is conceivable that young persons and the elderly may be present within flats. forming part of families. In addition, there may also be lone workers, visitors on the premises, and occupants with varying degrees of physical/mental impairment.

**3. Fire Safety Legislation**

**3.1 The following fire safety legislation applies to these premises**

Regulatory Reform (Fire Safety) Order 2005

**3.2 The above legislation is enforced by**

Nottinghamshire Fire and Rescue Service

**3.3 Other key fire safety legislation (other than Building Regs 2000)**

Housing Act 2004

**3.4 The other legislation referred to above is enforced by**

Local Authority.

---

**3.5 Guidance used as applicable to premises and occupation**Home Office Fire Safety in  
Purpose Built Blocks

---

**3.6 Is there an alteration or enforcement notice in force?**

Unknown

None apparent and no information available.

---

**3.7 Fire loss experience (since last FRA)**

Unknown

None apparent and no information available.

---



## Detailed Risk Assessment Part 2

8 actions

### A - Electrical Ignition Sources

A1

**Is the fixed electrical installation periodically inspected and tested, (include dates if known)?**

Yes

No mains electrical intake equipment noted, however refer to policy principle.

Policy Principle: FHG complete Fixed wire testing in line with current regulations every 5 years and complete an annual visual inspection on all properties.

A2

**Is PAT testing in common areas carried out?**

N/A

No portable electrical appliances observed in common parts.

Policy Principle: PAT testing is complete at the time of the visual inspection as mentioned above. All items in the communal areas will be tested.

A3

**Is there a policy for personal electrical appliances (consider restrictions of communal supply points such as outlets and T pin outlets)?**

N/A

No personal electrical appliances noted in the common area.

Policy Principle: PAT testing is complete at the time of the visual inspection as mentioned above. All items in the communal areas will be tested.

A4

**Is the use of adapters and leads limited?**

N/A

No adapters or leads noted in the common area at the time of assessment.

A5

**Are there any PV cells installed and do they have the appropriate isolation systems and signage to assist the fire and rescue service?**

N/A

None noted in the common area.

### B - Smoking Policies

1 action

B1

**Are there suitable arrangements to prevent fire as a result from smoking?**

Yes

Smoking is not permitted in the common area, residents are permitted to smoke in their own flats only. Refer to policy principle.

Policy Principle: No smoking policy in all communal areas- signage displayed.

B2

1 action

**Is the policy being adhered to and are "No smoking" signs provided in the common areas?**

Yes

No evidence of illicit smoking at time of assessment and no smoking signage was not provided in the common area.

**Open** | Priority: Medium | Due: 28 Apr 2024 7:58 PM BST | Created by: Jamie Yarwood

B2

Provide a no smoking sign on the wall of the open staircase at ground floor.

**Action/Recommendation Required?**

Yes

**Action Priority:**

Medium - 3 Months

C - Arson

C1

**Are premises secure against arson by outsiders? (Please state how)**

Yes

Ground floor flats are accessed directly from outside and upper floor flats are accessed from an open deck served by a staircase with open access. All flats have individual locking mechanisms.

C2

**Are bins secured or fire loading stored in a suitable location? (Please state bin type, location, if and how it is secured)**

Yes

Dedicated bin storage area located to the rear of and sufficiently away from the building considered satisfactory at time of inspection.




Photo 9

D - Portable Heaters and Installations

D1

**If used, is the use of portable heaters regarded as safe?**

N/A

No portable heating equipment noted in common parts at the time of the assessment.

D2

**Are fixed heating systems maintained annually?**

N/A

No fixed heating installations noted within the common parts at the time of the assessment, refer to policy principle.

Policy Principle: All Safety inspections carried out annually by qualified persons.

E - Cooking

E1

**Are reasonable measures in place to prevent fires as a result of cooking, including replacing filter(where necessary)?**

N/A

No cooking facilities provided in the common area.

F - Lightning

1 action

F1

1 action

**Does the building have a lightning protection system?**

No

No lightning protection on the building noted.

**Open** | Created by: Jamie Yarwood

F1

Recommend management undertake a risk assessment of the building to determine if lightning protection is required.

Policy Principle: No lightning protection policy in place

**Action/Recommendation Required?**

Yes

**Action Priority:**

Recommendation - No Timescale

G - Housekeeping

1 action

G1

**Are combustible materials kept away from any sources of ignition, including gas and electrical intake cupboards?**

Yes

No combustible material noted in the vicinity of any sources of ignition at the time of assessment.

G2

1 action

**Are the escape routes kept clear of items combustible materials or waste and free of any trip hazards?**

No

Potted plants noted on the first floor open deck.



Photo 10

**Open** | Priority: Low | Due: 28 Jan 2025 8:03 PM GMT | Created by: Jamie Yarwood

G2

Potted plants as noted should be removed from the open deck and residents advised not to use the open deck for storage of personal items.

**Action/Recommendation Required?**

Yes

**Action Priority:**

Low - 12 Months

G3

**Are mobility scooters or electric vehicles stored in the means of escape? If yes has an assessment been undertaken in line with the NFCC "Mobility Scooter Guidance for Residential Buildings"?**

N/A

No mobility scooters or electric vehicles noted in the common area at the time of assessment.

H - Hazards Introduced by Contractors

H1

**Is there satisfactory control over works carried out in the building by contractors (e.g. hot work permits)?**

Yes

All contractors must submit RAMS for procurement processes, and these are reviewed annually by FHG. A specific risk assessment is to be completed for each job.

I - Dangerous Substances

I1

**If dangerous substances are used, has a risk assessment been carried out as required by the Dangerous Substances and Explosives Atmospheres Regulations 2002 and are they stored correctly?**

N/A

General needs block with no dangerous substances noted in the common area at the time of assessment.

Policy Principle: All contractors must submit RAMS for procurement processes, and these are reviewed annually by FHG. A specific risk assessment is to be completed for each job.

## J - Other Significant Hazards

J1

**Are all issues deemed satisfactory? [1]**

Yes

No other issues noted at the time of assessment.

J2

**Are all issues deemed satisfactory? [2]**

N/A

## K - Means of Escape

K1

**Is the escape route design deemed satisfactory? (Consider current design codes)**

Yes

Escape route design appears to comply with current guidance documents and is considered satisfactory.

K2

**Is the fire-resisting construction (including any glazing) protecting escape routes and staircases of a suitable standard and maintained in sound condition?**

Yes

Fire resisting construction protecting the escape route is considered satisfactory, however refer to L1.

K3

**Is there adequate provision of exits (including exit Widths) for the numbers who may be present?**

Yes

Exit width is considered satisfactory for the expected numbers in the building.

K4

**Are doors on escape routes easily opened? (and are sliding or revolving doors avoided?)**

N/A

Ground floor flats discharge directly to outside and upper floor flats are provided with an external staircase with open access.

K5

**Do final exits open in the direction of escape where necessary?**

N/A

K6

**Are travel distances satisfactory? (consider single direction and more than one direction, property risk profile and occupancy characteristics)**

Yes

Travel distances are considered to be in accordance with current guidelines considered satisfactory.

K7

**Are there suitable precautions for all inner rooms?**

N/A

No inner rooms noted in the common area.

K8

**Are escape routes separated where appropriate?**

N/A

Single escape route considered satisfactory.

K9

**Are corridors sub-divided where appropriate?**

N/A

No corridors requiring sub-division provided in the building.

K10

**Do escape routes lead to a place of safety?**

Yes

Staircase allows escape at ground floor away from the building.




Photo 11

K11

**Are the stairs and/or lobbies provided with adequate ventilation? (If considered satisfactory, please state provision)**

Yes

Staircase is provided with open access and upper floor flats are accessed from an open deck considered satisfactory.



Photo 12

K12

**Are there any other issues that could affect the means of escape, for example plastic conduit/loose cables not secured by fire rated fastening?**

N/A

Considered satisfactory at the time of assessment.

L - Flat Entrance Doors

1 action

L1

1 action

**Are the sample inspection flat entrance door or doors in good condition and appropriately fire rated?**

Unknown

It was unable to be confirmed if flat entrance doors offer 30 minutes fire resistance. Ineffective flat entrance doors in a fire condition may allow smoke heat and fire to spread; this may impede escape and may cause physical harm to the occupants of the building. Flat F presents a passing risk.



Photo 13



Photo 14




Photo 15



Photo 16




Photo 17



Photo 18



Photo 19

**Open** | Priority: Medium | Due: 28 Apr 2024 8:27 PM BST | Created by: Jamie Yarwood

L1

Management to confirm that adequate FD30 certification is present for the flat entrance door as noted. If certification is unavailable, then a fire door survey should be undertaken to the flat entrance door by a competent 3rd party accredited company. Any recommendations from such a survey should be implemented as soon as practicable.

**Action/Recommendation Required?**

Yes

**Action Priority:**

Medium - 3 Months

M - Common Area Fire Doors

M1

**Are all common area fire door and frames in good condition and appropriately fire rated?**

N/A

No common area doors provided on the means of escape.

## N - Emergency Lighting

N1

**If emergency lighting is provided, is the coverage sufficient and in good repair? (Internal and external)**

Yes

Emergency lighting system was provided throughout the common area appearing to conform to BS 5266.



Photo 20

N2

**If EL not provided, is borrowed/artificial lighting sufficient for escape? (Internal and external)**

N/A

Refer to N1.

## O - Fire Safety Signs and Notices

O1

**Is there adequate provision of visible fire safety signs and notices? (Consider directional, exits, stairs, fire action notices, Fire door keep shut, fire equipment and 'do not use lift' signage)**

No

Fire action notice provided clearly indicating the stay put evacuation strategy for the building.



Photo 21

O2

**Wayfinding Signage (buildings over 11 metres in height). Are there clear markings for flat and floor recognition provided?**

N/A

## P - Means of Giving Warning in Case of Fire

1 action

P1

**Is a reasonable fire detection and fire alarm system provided in the common areas, where necessary?**

N/A

No common area fire detection and alarm system installed in the common area, considered satisfactory for



this purpose built building operating a stay put evacuation strategy.

P2

**If installed, is the common area AFD adequate for the occupancy and fire risk?**

N/A

Refer to P1.

P3

**If not installed, are the premises deemed safe without a common area AFD system?**

Yes

Refer to P1.

P4

**If there is a communal fire detection and fire alarm system, does it extend into the dwellings?**

N/A

Refer to P1.

P5

**Where appropriate, has a fire alarm zone plan been provided?**

N/A

Refer to P1.

P6

**Where appropriate, are there adequate arrangements for silencing and resetting an alarm condition?**

N/A

Refer to P1.

P7

1 action

**If applicable, is a separate domestic hard-wired smoke/heat alarm within the flats installed to a suitable standard?**

Unknown

No access to individual flats at time of inspection to check for hard wired smoke alarms.

**Open** | Priority: Medium | Due: 28 Apr 2024 8:31 PM BST | Created by: Jamie Yarwood

P7

It is recommended that each flat is checked to confirm that BS5839-6:2019 Grade D, LD2 detection is fitted.

**Action/Recommendation Required?**

Yes

**Action Priority:**

Medium - 3 Months

P8

**If applicable (Sheltered scheme) is the smoke detection within the flats monitored by an alarm receiving centre/on site scheme manager via a telecare system?**

N/A

Q - Measures to Limit Fire Spread and Development

1 action

Q1

**Is there adequate levels of compartmentation between floors and between flats and the common escape routes?**

Yes

From visual inspection only, compartmentation appears satisfactory.

Q2

**Are hidden voids appropriately enclosed and/or fire-stopped? (consider above suspended ceilings)**

N/A

No hidden voids noted at the time of assessment.

Q3

**Is there adequately fire protected service risers and/or ducts in common areas, that will restrict the spread of fire and smoke?**

N/A

No service riser cupboards or ducts noted in the common area means of escape.

Q4

1 action

**Is compartmentation maintained in the roof space?**

Unknown

No access to any roof void above individual flats.

**Open** | Priority: Medium | Due: 28 Apr 2024 8:35 PM BST | Created by: Jamie Yarwood

Q4

Management to check the compartmentation between individual dwellings, any breaches in compartmentation are recommended to be rectified by a competent third party company.

**Action/Recommendation Required?**

Yes

**Action Priority:**

Medium - 3 Months

Q5

**Are electrics, including embedded meters, enclosed in fire rated construction?**

N/A

No mains electrical intake cupboard provided in the common area means of escape.

Q6

**As far as can reasonably be ascertained, are fire dampers provided as necessary to protect critical means of escape against passage of fire, smoke and products of combustion in the early stages of a fire?**

N/A

Dampers are not considered a requirement in this building.

Q7

**Is there reasonable limitation of linings to escape routes that might promote fire spread?**

Yes

Linings to escape routes are considered satisfactory.

Q8

**Are soft furnishings in common areas appropriate to limit fire spread/growth?**

N/A

No soft furnishings provided in the common area.

Q9

**Does the premises have any external balconies, cladding or materials which may promote external fire spread?**

N/A

Brick faced external fascia, considered satisfactory.



Photo 22

Q10

**Has a note been prepared of the external walls of the building and details of construction materials used? Does the note include and identify the level of risk that the design and materials used?**

N/A

Refer to Q9.

Q11

**Does the External wall note include any mitigating circumstances that may have been taken to reduce the risk?**

N/A

Refer to Q9.

Q12

**Has the responsible person reviewed the external wall note on a regular basis and revised it if there have been any significant changes in the external walls.**

N/A

Refer to Q9.

Q13

**Are all other fire spread/compartmentation issues satisfactory?**

Yes

No other compartmentation issues noted at the time of inspection.

R - Fire Extinguishing Appliances

R1

**If required, is there reasonable provision of accessible portable fire extinguishers?**

N/A

No portable fire extinguishers provided and are not considered a requirement.

S - Relevant Automatic Fire Extinguishing Systems

S1

**Are there any automatic fire suppressant systems on site?**

N/A

No automatic fire suppression systems noted in the block.

S2

**Are there any fixed fire fighting mains within the premises?**

No

Building is not provided with a fire fighting main.

S3

**If any other relevant systems / equipment is installed, state type of system and comment as necessary**

N/A

No other relevant systems noted at the time of assessment.

T - Procedures and Arrangements

1 action

T1

**Recommended evacuation strategy for this building is:**

Stay Put

T2

**Has a competent person(s) been appointed to assist in undertaking the preventative and protective measures**

Yes

including in house checks?

Futures are responsible and have a fire safety team to undertake the preventative and protective measures across their housing stock.

T3

**Are there appropriate documented fire safety arrangements and procedures in place in the event of fire?**

Yes

Refer to O1.

T4

**Are there suitable arrangements for liaison and calling the Fire Service?**

Yes

General needs block, residents are expected to summon the fire service.

T5

**Are there suitable fire assembly points away from any risk?**

N/A

In the event of a resident needing to evacuate the premises in an emergency, the assembly point would be any safe place clear of the building.

T6

1 action

**Are there adequate procedures in place for the evacuation of disabled people who are likely to be present?**

Unknown

Unknown if suitable arrangements were in place for any persons within the premises with disabilities.

**Open** | Created by: Jamie Yarwood

T6

PEEPs are currently not applicable in general needs properties, however a Person-Centred Fire Risk Assessment (PCFRA) may be appropriate, if a resident has been identified as especially vulnerable and at risk from fire hazards in their property. It is recommended that the provider works with the identified vulnerable resident or their representative to help to reduce risk from fire and where necessary involve other agencies. In addition refer to Y1.

**Action/Recommendation Required?**

Yes

**Action Priority:**

Recommendation - No Timescale

T7

**Are staff nominated and trained on the use of fire extinguishing appliances?**

N/A

Building not permanently staffed and no fire extinguishers provided.

T8

**Are staff nominated and trained to assist in evacuation (Where applicable e.g. Offices, supported schemes)?**

N/A

No staff present in the building, residents are expected to self-evacuate.

U - Training

U1

**Do staff receive adequate induction and annual refresher fire safety training? (To include fire risks in the premises, fire safety measures in the building, action in the event of fire and on hearing alarm, location and use of fire extinguishers, calling the fire service)**

Unknown

No permanent staff presence in the building, therefore not applicable in this instance.

Policy Principle: All touchdown points (small offices) staff receive Inductions and annual refreshers on fire safety fire safety. But at all the schemes no permanent staff are present.

U2

**Are employees nominated to assist in the event of fire given additional training?**

N/A

No permanent staff in the building.

V - Testing and Maintenance

V1

**Are all fire safety provisions for the building (AFD, Emergency Lighting, sprinklers etc.) routinely tested and maintained?**

Yes

See Policy Principle.

Policy Principle: Alarms- FHG Greenscapes, MITIE. E/L- FHG Greenscapes, MITIE. Assets Surveyor Extinguishers- MITIE. Fire Doors- FHG Greenscapes, Assets Surveyor Final Exits/ Escape Routes- Greenscapes/ Neighbourhoods.

W - Records

W1

**Is all routine testing and staff training including fire drills suitably recorded and available for inspection?**

N/A

Fire drills not considered a requirement in this general needs block.

X - Premises Information Box

X1

**Is a Premises Information Box located at the premises accessible to the Fire and Rescue Service, secure from unauthorised access and kept up to date?**

N/A

No premises information box provided and not considered a requirement.

Policy Principle: Log book is kept on SharePoint with proposed specific QR code access.

Y - Engagement with Residents

1 action

Y1

1 action

**Has all Fire Safety information & procedures been disseminated to the residents?**

Unknown

No information available at the time of assessment.

**Open** | Created by: Jamie Yarwood

Y1

Management to confirm that information on fire procedures are shared with residents on sign-up of the property, with regular updates on their website, property notice boards, specific mailings etc.

**Action/Recommendation Required?**

Yes

**Action Priority:**

Recommendation - No Timescale

Z - Any Other Information

Z1

**Are all issues deemed satisfactory? [1]**

Yes

No other issues noted at the time of assessment.

Z2

**Are all issues deemed satisfactory? [2]**

N/A

## Assessment Risk Ratings

2 flagged

### Risk Rating

The following simple risk level estimator is based on a more general health and safety risk level estimator of the type contained in BS 8800:

Likelihood of fire	Potential consequences of fire		
	Slight Harm	Moderate Harm	Extreme Harm
Low	Trivial	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

### Likelihood of Fire

Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at these premises is:

MEDIUM

In this context, a definition of the above terms is as follows:

**Low:** Unusually low likelihood of fire as a result of negligible potential sources of ignition.

**Medium:** Normal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).

**High:** Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.

### Potential Consequences of Fire

Taking into account the nature of the building and occupants, as well as the fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the consequences for life safety in the event of fire would be:

MODERATE HARM

### Potential Consequences of Fire

In this context, a definition of the above terms is as follows:

**Slight harm:** Outbreak of fire unlikely to result in serious injury or death of any occupant.

**Moderate harmful:** Outbreak of fire could foreseeably result in injury (including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.

**Extreme harm:** Significant potential for serious injury or death of one or more occupants likely to involve multiple fatalities.

### Premises Risk Rating

1 flagged

Accordingly, it is considered that the risk to life from fire at these premises is:

MODERATE



A suitable risk-based control plan should involve effort and urgency that is proportional to risk. The following risk-based control plan is based on one advocated by BS 8800 for general health and safety risks:

Risk Level	Action and time table
Trivial	No action is required and no detailed records need be kept.
Tolerable	No major additional controls required. However, there might be a need for improvements that involve minor or limited cost.
Moderate	It is essential that efforts are made to reduce the risk. Risk reduction measures should be implemented within a defined time period. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measures.
Substantial	Considerable resources might have to be allocated to reduce the risk. If the building is unoccupied, it should not be occupied until the risk has been reduced. If the building is occupied, urgent action should be taken.
Intolerable	Building (or relevant area) should not be occupied until the risk is reduced.

*(Note that, although the purpose of this section is to place the risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly.)*

**On satisfactory completion of all remedial works the risk rating of this building may be reduced to**

**TOLERABLE**

## Limitations Statement

### Fire Risk Assessment – Limitations

The purpose of the fire risk assessment is solely to provide an assessment of the risk to life from fire, and, where appropriate, to make recommendations to reduce the risk to life from fire. This assessment does not address fire risks to property or business continuity.

Under Article 5(4) of the Regulatory Reform (Fire Safety) Order 2005 or other devolved equivalent regional legislation and relevant United Kingdom law, we have been appointed to provide advice to the Responsible Person only. We have no control over any part of the premises covered within this fire risk assessment, and we have no responsibility for undertaking any of the recommendations made. The assessment is intended to assist the Responsible Person to comply with their responsibilities under the Regulatory Reform (Fire Safety) Order 2005.

Any policy principles included within this Fire Risk Assessment have been provided by the responsible person or their representative and been added in good faith. We cannot take responsibility for the accuracy of the policy principles with regard to the client's internal policies, British Standards or codes of practice.

Any test certificates supplied as part of the Fire Risk Assessment process will be considered but we take no responsibility or liability whatsoever is accepted for the accuracy of such information supplied by others.

The findings of the fire risk assessment will be based upon the conditions found at the Premises at the time the assessment is to be carried out and on relevant information provided by the Responsible Person or others either prior to, during or after the Fire Risk Assessment of the premises.

We consider the External Wall System as part of the Fire Risk Assessment process, however, we take no responsibility for a fire risk appraisal of external wall construction on existing buildings and work to the guidance and limitations detailed in PAS 9980:2022 0.2 Fire risk assessments. Any information supplied to the Fire Risk Assessor is taken in good faith and we accept no responsibility for the accuracy of the information supplied.

No responsibility is accepted for any change in the conditions or circumstances prior after the Fire Risk Assessment has been undertaken.

It is stressed that the assessment should not be regarded as a structural survey for fire safety purposes as such a survey should only be entrusted to a qualified building surveyor. The Fire Risk Assessment did not involve destructive exposure (Unless specifically requested as part of a contractual arrangement), and therefore it is not always possible to survey less readily accessible areas. It is, therefore, necessary to rely on a degree of sampling and also reasonable assumptions and judgements.

All services or penetrations traversing fire resisting compartments are not confirmed as being sufficiently fire stopped with fire resisting material to the appropriate standard. If fire compartments\fire dampers\voids (ceilings, floors or other voids) are considered inaccessible for safety reasons or any other reason and cannot be physically accessed or are outside the visual range of the assessor, technical comment on these areas cannot be provided.

This fire risk assessment will not necessarily identify all minor fire-stopping issues that might exist within the building and should be considered to be a sample of fire compartmentation. Unless a full fire compartmentation survey is contractually included within the scope of the assessment. If there are reasons to suspect the fire resistance within the Premises has not been sufficiently maintained the responsibility to provide this technical information rests with the Responsible Person\duty holder.

This fire risk assessment will not necessarily identify all minor fire door issues that might exist within the building and should be considered a sample of fire doors. Unless a full fire door survey is contractually included within the scope of the assessment.

A full investigation of the design of heating, ventilation and air conditioning (HVAC) systems is outside the scope of this fire risk assessment.

Although reference in the report may be made to relevant British Standards, Codes of Practice and Guides the assessment will not, nor is it intended to, ensure compliance with any of the documents referred to in the assessment. However, deviations from generally accepted codes, standards and universally recognised good fire safety practice will be identified in the assessment.

Where an emergency escape lighting system is present, comments are based upon a visual assessment of the system coverage and condition, but no illuminance tests or verification of the installation to the relevant British Standards were carried out.

Where a fire alarm system is present, comments are based upon a visual assessment, but no audibility tests or verification of full compliance with the relevant British Standards were carried out.

Where manual firefighting equipment is present, comments are based upon a visual assessment, but no verification of full compliance with the relevant British Standards or codes of practice were carried out.

It is the expectation that any reference to the testing and maintenance of passive or active fire protection systems within the premises are undertaken to the relevant current British Standards, Codes of Practice and Guides it is the responsible person's duty to ensure this is undertaken.

There will be a brief review of procedures at the time of this fire risk assessment. An in-depth review of documentation is outside the scope of this fire risk assessment, unless otherwise stated in the contract.

The report will highlight the Significant Findings (Split into Recommendations and Action(s)) that the Fire Risk Assessor found at the time of the assessment.

It is the responsibility of the Responsible Person to ensure that any deficiencies found during the assessment and subsequently reported to the Responsible Person, by the report or other means, are their responsibility to rectify to a satisfactory standard to meet the requirements of the Regulatory Reform (Fire Safety) Order 2005.

It is wholly the responsibility of the Responsible Person and/or their agent to implement and maintain the Fire Precautions at the Premises to a satisfactory standard and condition to comply with the requirements of the Regulatory Reform (Fire Safety) Order 2005.

Failure to address and/or rectify any deficiencies mentioned in the report may result in serious harm, injury and or death to any relative person, employee, visitor, you or any other person in, on, within or without the perimeter of the Premises.

Failure to address any of the deficiencies highlighted in the report may be considered to be a breach of the Regulatory Reform (Fire Safety) Order 2005 and may result in prosecution by the enforcing authority.

Responsibility for the ongoing management of the Premises and even, if necessary, the decision to allow the Premises to be used for their present purpose, and in the current condition remains with the Responsible Person.

Responsibility for management procedures regarding, evacuation management, and maintenance of firefighting equipment, Fire alarms systems, emergency escape lighting, and any other emergency-related provisions remains a duty of the responsible person, not the fire risk

assessor as this is not within their control.

Any faults or deficiencies in any emergency emergency-related staffing levels and/or staff training are the responsibility of the Responsible Person and/or the duty holder.

Portable or moveable items and items brought into the Premises are the responsibility of the Responsible Person and/or the duty holder.

It is recommended that the Assessment is reviewed annually or when there is a significant change, material alteration, change in the use of the Premises, a change in working practices, or following any incident, including fire, which may affect the Fire Precautions of the Premises.

The circumstances of the Premises may change over time and with use and/or occupancy, therefore, failure to review the fire risk assessment by the date indicated may mean that the fire risk assessment is no longer valid.

This Fire Risk Assessment is not a Health and Safety Report. A Health and Safety review should be conducted to ensure compliance with the Health and Safety at Work Act 1974.

Compliance with all other legislation is the responsibility of the Responsible Person. We accept no responsibility for loss, damage or other liability arising from a fire, loss and/or injury due to the failure to observe the safety, observance and practises identified in the Assessment

The Responsible Person will always remain responsible for the outcome of the Fire Risk Assessment and/or its review. This includes the accuracy of details contained within this report.

By signing for, by payment for services or acknowledgement of receipt of the report you accept full responsibility and accountability for implementing the findings of the report.

---



## Life Safety Fire Risk Assessment Certificate of Conformity

This certificate is issued by the organization named in Part 1 of the schedule in respect of the fire risk assessment provided for the person(s) or organization named in Part 2 of the schedule at the premises and / or part of the premises identified in Part 3 of the schedule

### Schedule

<b>Part 1a - Name and Address of Certified Organisation</b>	Pennington Choices Limited
<b>Part 1b - BAFE Registration Number of Issuing Certified Organisation</b>	102119
<b>Part 1c - SSAIB 3rd Party Certificate Number</b>	CHES077
<b>Part 2 - Name of Client</b>	Futures Housing Group
<b>Part 3a - Address of premises for which the Fire Risk Assessment was carried out</b>	Apartments 67A-G Hallam Road: NG3 6HR
<b>Part 3b - Part or parts of the premises to which the Fire Risk Assessment applies</b>	Open deck, staircase, landing, escape routes internal and external.
<b>Part 4 - Brief description of the scope and purpose of the Fire Risk Assessment</b>	Life Safety (as agreed spec)
<b>Part 4b - Limitations of FRA</b>	See Limitations Statement
<b>Part 5 - Effective Date of the Fire Risk Assessment</b>	28 Jan 2024
<b>Part 6 - Recommended Date for Reassessment of the premises</b>	28 Jan 2026
<b>Part 7 - Unique Reference Number of this Certificate (Job Number)</b>	173605

Signed for on behalf of the Issuing Certified Organisation

James Hutton



---

**Dated:**

28 Jan 2024

---

SSAIB, 7-9 Earsdon Road, West Monkseaton, Whitley Bay, Tyne & Wear. NE25 9SX

BAFE, The Fire Service College, London Road, Moreton-in-Marsh, Gloucestershire, GL56 0RH  
01608 653 350 | [info@bafes.org.uk](mailto:info@bafes.org.uk) | [www.bafes.org.uk](http://www.bafes.org.uk)

---

## Media summary



Photo 1




Photo 2




Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14





Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22