

FIRE RISK ASSESSMENT

PROPERTY ASSESSED: De Senlis, Jerome Court Northampton Northampton

NN3 5GA



UPRN: DES601-BLK Inspection Date: 01/08/2022 Validation Date: 25/08/2022

Valid to: 25/08/2023


FRA completed by: Pennington Choices

FRA Completed For: Futures




Executive Summary





FRA Action by Type			
Recommendations: 5			
Actions:	7		



Premises Risk Rating: Moderate

Reassessment Priority: High - 1 Year

Recommended evacuation strategy for this building is: Stay Put

On satisfactory completion of all remedial works the risk rating of this building may be reduced to:: Tolerable

FRA - Summary

Responsible Person	CEO Futures
Property Designation	General needs
Management Extent	Partially Managed Building - Manager or Senior Staff not onsite regularly
No of Floors	3
No of Flats (if applicable)	6
Ground floor Area (m2)	60
Total Area of all floors (m2)	360

FRA Completed By:	Gary Broadhurst
FRA Type:	Type 1
QA Validation Date:	25/08/2022
QA Carried Out By:	Piotr Iwan
Validator's Signature:	~n



High		
Elian		

Ref.	Category		Priority	Complete By
P7	Means Of Giving Warning In Case Of Fire		High	24/Sep/2022
Finding/Observation Action/Recommendation		n		
	vas accessed to identify it is provided with heat in the kitchen and smoke detector in the hallway.	all circumstances". Howe detectors should be instal detector should be instal Where more than one ro habitable room, a smoke of these rooms". It is rec	should be considered the mini- ever, BS 5839-6:2019 states talled in every kitchen. A smok led in the principal habitable rom might be used as the prince detector should be installed ommended that each flat is characteristics.	hat "heat e coom. cipal in each necked to

Ref.	Category		Priority	Complete By
Q9	Measures To Limit Fire Spread And Development		High	24/Sep/2022
Finding/Observation		Action/Recommendation		
The balconies are constructed of galvanised steel although the decks are wooden, and vehicles were parked beneath a balcony. Wooden furniture was also seen stored on one of the balconies.			ndent surveys on the balconie comote fire spread or affect es	

Image: Q91





Medium		
Medilim		
MEGUIUIII		

Ref.	Category		Priority	Complete By
H1	Hazards Introduced By Contractors		Medium	23/Nov/2022
Finding/Observation Action/Recommendation		on		
No policy available to determine if satisfactory control over works are carried out in the building for in-house contractors and outside contractors (e.g. hot work permits).		safe practices to be carri documented procedure i contractors are controlled approved industry standa work and a hot work peri	ded at the main entrance inced out by all visiting contracts recommended for ensuring don site and only operate wards. This should include a part procedure where approprised of the emergency produced	tors. A g all ithin permit to riate. All

Ref.	of. Category		Priority	Complete By	
Q4	Measures To Limit Fire Spread And Development		Medium	23/Nov/2022	
Finding/0	Finding/Observation Action/Recommendation		1		
No acces			Management to confirm that appropriate separation is maintained in the roof spaces.		



Ref.	Category		Priority	Complete By
Q6	Measures To Limit Fire Spread And Development		Medium	23/Nov/2022
Finding/Observation		Action/Recommendation		
No evidence is kept for inspection on site.		Management should confirm that where and if required fire dampers are provided as required.		d fire

Ref.	Ref. Category		Priority	Complete By
S3	Relevant Automatic Fire Extinguishing Systems		Medium	23/Nov/2022
Finding/Observation		Action/Recommendation		
A fixed standpipe is provided outside the building which is also locked and it is not understood what it is provided for and who can use it.			ify and use appropriate signa pipe is for and who can use	•

Image: S31



Ref.	Category		Priority	Complete By
V1	Testing And Maintenance		Medium	23/Nov/2022
Finding/Observation Action/Recommendation		n		
All fire sa	ciple answer. Ifety provisions must be tested in accordance with the standards and guides.	accordance with BS 767 Automatic opening vents must be tested and main EN12101-2.	st be tested and maintained in 1. (AOV) are provided on site votained in accordance with BS all the inspected and checked the control of the	vhich

Image: V11





No Timescale 5

Ref.	Category		Priority	Complete By
C2	2 Arson		No Timescale	
Finding/Observation		Action/Recommendation		
Waste and recycling are stored inside a dedicated bin store		It is recommended that a store for the emergency	sign is displayed outside the services	bin

Image: C21



Ref.	tef. Category		Priority	Complete By
F1	F1 Lightning		No Timescale	
Finding/Observation		Action/Recommendation		
No lightning protection system was identified during the assessment.			nt undertake a risk assessme if lightning protection is requi	

Ref.	Category		Priority	Complete By
Q10	Measures To Limit Fire Spread And Development		No Timescale	
Finding/Observation		Action/Recommendation		
The visiting officer reported that the external surface wall finishing's have been assessed independently and require no further action. See main picture.		single access/exit door it assessment of external v	ace finishing's extend to the si is recommended that the cur vall surface finishing's is re to account if this has not alrea	rent risk



Ref.	Category		Priority	Complete By
T6	Procedures And Arrangements		No Timescale	
Finding/Observation		Action/Recommendation	Action/Recommendation	
Unable to confirm at the time of the assessment.		out on all tenants in gene	Person Centered Fire Risk Assessments should be carried out on all tenants in general needs property, when required, and should be reviewed on an annual basis.	
		and should be reviewed	on an annual basis.	

Ref.	Category		Priority	Complete By
Y1	Engagement With Residents		No Timescale	
Finding/Observation		Action/Recommendation	Action/Recommendation	
It is important to ensure residents are kept informed			Safety information should be regularly updated to residents using different formats including letters, social media and posters etc	
		posters etc		



Reassessment Priority	High - 1 Year
Responsible Person	CEO Futures
BAFE Cert	CHES077

General Information

UPRN	DES601-BLK
Address	De Senlis, Jerome Court Northampton Northampton
Postcode	NN3 5GA
Fire Risk Assessor	Gary Broadhurst
Date of Inspection	01/08/2022
Checked by	Piotr Iwan
Reassessment Date	01/08/2023

General Information

Property Designation	General needs
Property Type	Purpose built block of flats
No of Floors	3
No of Flats (if applicable)	6
Ground floor area (m2)	60
Total area of all floors	360
Building Description	De Senlis House. The purpose-built 3 storey block of flats is detached and stands back from the road in a Cul-De-Sac with parking areas at the front of the property, including vehicles parked directly beneath the balconies which have wooden decked floors. The building has 3 floors, is traditionally constructed of brick with 3 flats on each floor level above ground floor, as the ground floor has no apartments but has a lobby, bin store and bike store The property has one exit door which is the main entrance door, and all flats and common area doors have recently been provided with new FD30S certificated fire doors. The front wall is provided with a fireman's switch to override the entrance door which is provided with overhead self-closing device, thumb turn lock inside and secure electronic fob access The front wall has part covering of wooden cladding however the visiting officer reported that an independent survey had been carried out which was all clear and no further action is required Balconies are provided on the front elevation which are constructed of Galvanised steel although the decking is constructed of wood

	The windows on the stairs are fixed although an AOV is provided at the head of the stairs with override and reset button on the ground floor Waste bins are stored inside the property in a dedicated store which has double access doors on the outside of the building. It is recommended that the bin store is signed externally for the emergency services The open plan single stairs and landings provide access to the upper floor apartments and the stairs were clear of obstruction and in good condition The property is not provided with a common area fire alarm system although it is provided with escape lighting and AOV which is connected to a manual switch and smoke detector on the stairs for automatic opening. There is no provision of firefighting equipment although signage was considered adequate and included, general fire action notice, no smoking, Fire door keep shut and exit/running man signs Access was provided into flat 15 at the doorway and the resident informed that the flat is provided with smoke detector in the hall linked to a heat detector in the kitchen Overall, the property appeared well kept, and clean and tidy, and the electric cupboard was locked shut
Building Construction	Traditional brick with pitched and tiled roof
Extent of common areas	Bin store, bike store, stairs and lobbies
Areas of the building to which access was not available	Roof space and flats
If applicable state which flats were sample inspected	15



1. The Occupants

Ref.	Question	Policy Principles
10	Management Extent	
Answer		Finding/Observation
Partially regularly	Managed Building - Manager or Senior Staff not onsite	
Ref.	Question	Policy Principles
11	Details of any onsite management (hours onsite etc.)	
Answer		Finding/Observation
Unknow	n.	
Ref.	Question	Policy Principles
12	Person managing fire safety in premises	
Answer		Finding/Observation
Shared	responsibilities between Future and residents	
Ref.	Question	Policy Principles
13	Person consulted during the fire risk assessment	
Answer		Finding/Observation
Ben Wo	od	
Ref.	Question	Policy Principles
14	Number of occupants (maximum estimated)	
Answer		Finding/Observation
12		
Ref.	Question	Policy Principles
15	Approximate maximum number of employees at any one time	
Answer		Finding/Observation
1		
Ref.	Question	Policy Principles
16	Number of members of the public (maximum estimated)	
Answer		Finding/Observation
6		



Ref.	Question	Policy Principles
17	Identify any people who are especially at risk: - sleeping occupants - disabled occupants - occupants in remote areas and lone workers - young persons - others	
Answe	r	Finding/Observation
This is a "general needs" block of flats that will have sleeping occupants. It is conceivable that there may be young persons, the elderly and children within the flats as part of families who reside there. There may also be occupants with varying degrees of physical/mental impairment. In addition, lone workers may be present within common parts of the premises.		



2. Fire Safety Legislation

Ref.	Question	Policy Principles
21	The following fire safety legislation applies to these premises	
Answer		Finding/Observation
Regulato	ory Reform (Fire Safety) Order 2005	
Ref.	Question	Policy Principles
22	The above legislation is enforced by	
Answer		Finding/Observation
Northam	ptonshire Fire and Rescue Service	
Ref.	Question	Policy Principles
23	Other key fire safety legislation (other than Building Regs 2000)	
Answer		Finding/Observation
Housing	Act 2004	
Ref.	Question	Policy Principles
24	The other legislation referred to above is enforced by	
Answer		Finding/Observation
Northam	pton Council	
Ref.	Question	Policy Principles
25	Guidance used as applicable to premises and occupation	
Answer		Finding/Observation
Home O Blocks	ffice (September 2021) Fire Safety in Purpose Built	
Ref.	Question	Policy Principles
26	Is there an alteration or enforcement notice in force?	
Answer		Finding/Observation
No		
Ref.	Question	Policy Principles
27	Fire loss experience (since last FRA)	
Answer		Finding/Observation
No		
· · · · · · · · · · · · · · · · · · ·		



A. Electrical Ignition Sources

Ref.	Question	Policy Principles	
A1	Is the fixed electrical installation periodically inspected and tested, (include dates if known)?	FHG complete Fixed wire testing in line with current regulations every 5 years and complete an annual visual inspection on all properties.	
Answer		Finding/Observation	
Yes		See principle.	
Ref.	Question	Policy Principles	
A2	Is PAT testing in common areas carried out?	PAT testing is complete at the time of the visual inspection as mentioned above. All items in the communal areas will be tested.	
Answer		Finding/Observation	
N/A		There are no portable electrical items in the common areas.	
Ref.	Question	Policy Principles	
A3	Is there a policy for personal electrical appliances (consider restrictions of communal supply points such as outlets and T pin outlets)?	All personal items are not to be left in communal areas. Mobility Scooter Policy	
Answer		Finding/Observation	
Yes		See principle.	
Ref.	Question	Policy Principles	
A4	Is the use of adapters and leads limited?		
Answer		Finding/Observation	
N/A			
Ref.	Question	Policy Principles	
A5	Are they any PV cells installed and do they have the appropriate isolation systems and signage to assist the fire and rescue service?		
Answer		Finding/Observation	
No			



B. Smoking Policies

Ref. Question		Policy Principles	
B1 Are there suitable arrangements to prevent fire as a result from smoking?		No smoking policy in all communal areas- signage displayed.	
Answer		Finding/Observation	
Yes		No smoking signage is displayed inside the property and there were no signs of smoking inside the property at the time of the assessment.	

Images

Image: B11



Ref.	Question	Policy Principles
B2	Is the policy being adhered to and are "No smoking" signs provided in the common areas?	
Answer		Finding/Observation
Yes		See B1



C. Arson

Ref. Question		Policy Principles	
C1 Are premises secure against arson by outsiders? (Please state how)			
Answer		Finding/Observation	
Yes		The front door was locked shut and is accessed by electronic key pad	

Images

Image: C11



Ref. Question		Policy Principles	
C2	Are bins secured or fire loading stored in a suitable location? (Please state bin type, location, if and how it is secured)		
Answer		Finding/Observation	
Yes		Waste and recycling are stored inside a dedicated bin store	

Images

Image: C21





D. Portable Heaters And Heating Installations

Ref.	Question	Policy Principles		
D1 If used, is the use of portable heaters regarded as safe?				
Answer		Finding/Observation		
N/A				
Ref.	Question	Policy Principles		
D2 Are fixed heating systems maintained annually?		All Safety inspections carried out annually by qualified persons.		
Answer		Finding/Observation		
N/A		No heating is provided in the common areas		

E. Cooking

Ref.	Question	Policy Principles
E1	Are reasonable measures in place to prevent fires as a result of cooking, including replacing filter(where necessary)?	
Answer		Finding/Observation
N/A		

F. Lightning

Ref. Question		Policy Principles	
F1 Does the building have a lightning protection system?		No lightning protection policy in place	
Answer		Finding/Observation	
No		No lightning protection system was identified during the assessment.	



G. House-Keeping

Ref.	Question	Policy Principles
G1	Are combustible materials kept away from any sources of ignition, including gas and electrical intake cupboards?	
Answer		Finding/Observation
Yes		

Ref. Question		Policy Principles	
G2 Are the escape routes kept clear of items combustible materials or waste and free of any trip hazards?			
Answer		Finding/Observation	
Yes		The internal escape routes including the stairs were free from items	

Images

Image: G21



Ref.	Question	Policy Principles
G3	Are mobility scooters or electric vehicles stored in the means of escape? If yes has an assessment been undertaken in line with the NFCC "Mobility Scooter Guidance for Residential Buildings"?	
Answer		Finding/Observation
No		



H. Hazards Introduced By Contractors

Ref.	Question	Policy Principles			
H1	Is there satisfactory control over works carried out in the building by contractors (e.g. hot work permits)?				
Answer Finding/Obse		Finding/Observation	g/Observation		
a		No policy available to determine if satisfactory control over works are carried out in the building for in-house contractors and outside contractors (e.g. hot work permits).			
Action/Recommendation			Priority	Due Date	
Signage should be provided at the main entrance indicating safe practices to be carried out by all visiting contractors. A documented procedure is recommended for ensuring all contractors are controlled on site and only operate within approved industry standards. This should include a permit to work and a hot work permit procedure where appropriate. All contractors should be advised of the emergency procedures and hazardous areas.		nmended n a hot work	Medium	23/Nov/2022	

I. Dangerous Substances

Ref.	Question	Policy Principles
I1	If dangerous substances are used, has a risk assessment been carried out as required by the Dangerous Substances and Explosives Atmospheres Regulations 2002 and are they stored correctly?	All contractors must submit RAMS for procurement processes, and these are reviewed annually by FHG. A specific risk assessment is to be completed for each job.
Answe	r	Finding/Observation
N/A		See principle.

J. Other Significant Hazards

Ref.	Question	Policy Principles	
J1	Are all issues deemed satisfactory? [1]		
Answe	r	Finding/Observation	
Yes			
Ref.	Question	Policy Principles	
J2	Are all issues deemed satisfactory?		
Answer		Finding/Observation	
Yes			



K. Means Of Escape

Ref.	Question	Policy Principles
K1	Is the escape route design deemed satisfactory? (Consider current design codes)	
Answe	r	Finding/Observation
Yes		A single stairs is provided with one exit door at the base of the stairs which is fitted with thumb turn device.
Images	:	



Image: K11

Ref.	Question	Policy Principles
K2	Is the fire-resisting construction (including any glazing) protecting escape routes and staircases of a suitable standard and maintained in sound condition?	
Answe	er	Finding/Observation
Yes		
Ref.	Question	Policy Principles
K3	Is there adequate provision of exits (including exit Widths) for the numbers who may be present?	
Answe	er	Finding/Observation
Yes		

Ref.	Question	Policy Principles
K4	Are doors on escape routes easily opened? (and are sliding or revolving doors avoided?)	
Answer		Finding/Observation
Yes		The main entrance door is provided with thumb turn device which was working as it should during the site visit.

Ref.	Question	Policy Principles
K5	Do final exits open in the direction of escape where necessary?	
Answer		Finding/Observation
Yes		



Ref.	Question	Policy Principles
K6	Are travels distances satisfactory? (consider single direction and more than one direction, property risk profile and occupancy characteristics)	
Answe	r	Finding/Observation
Yes		Travel distances are short from the upper floor to the final exit door.
Ref.	Question	Policy Principles
K7	Are there suitable precautions for all inner rooms?	
Answe	r	Finding/Observation
N/A		
Ref.	Question	Policy Principles
K8	Are escape routes separated where appropriate?	
Answe	r	Finding/Observation
N/A		
Ref.	Question	Policy Principles
K9	Are corridors sub-divided where appropriate?	
Answe	r	Finding/Observation
N/A		
Ref.	Question	Policy Principles
K10	Do escape routes lead to a place of safety?	
Answe	r	Finding/Observation
Yes		The flats lead to the stairs, landings and the final exit door.
Ref.	Question	Policy Principles
K11	Are the stairs and/or lobbies provided with adequate ventilation? (If considered satisfactory, please state provision)	
Answe	r	Finding/Observation
Yes		The landing windows are fixed however the head of the stairs is provided with AOV and the stairs are provided with automatic smoke detectors to actuate the AOV automatically in support of the manual override/reset button.

Images

Image: K112 Image: K111







Ref.	Question	Policy Principles
K12	Is there any other issues that could affect the means of escape, for example plastic conduit/loose cables not secured by fire rated fastening?	
Answer		Finding/Observation
No		

L. Flat Entrance Doors

Ref.	Question	Policy Principles
L1	Are the sample inspection flat entrance door or doors in good condition and appropriately fire rated?	
Answer		Finding/Observation
Yes		The flat entrance doors were installed and certificated by a third party accredited contractor as reported on site

Images

Image: L11



M. Common Area Fire Doors

Ref.	Question	Policy Principles
M1	Are all common area fire door and frames in good condition and appropriately fire rated?	
Answe	r	Finding/Observation
Yes		The common area fire doors are all in good condition and include the entrance door, bike store, bin store and electric cupboard.

Images

Image: M11





N. Emergency Lighting

Ref.	Question	Policy Principles
N1	If emergency lighting is provided, is the coverage sufficient and in good repair? (Internal and external)	
Answe	er	Finding/Observation
Yes		The escape lights cover the escape route which were identified by green LED lights.
Ref.	Question	Policy Principles
N2	If EL not provided, is borrowed/artificial lighting sufficient for escape? (Internal and external)	
Answe	r	Finding/Observation

O. Fire Safety Signs & Notices

Ref.	Question	Policy Principles
O1	Is there adequate provision of visible fire safety signs and notices? (Consider directional, exits, stairs, fire action notices, Fire door keep shut, fire equipment and 'do not use lift' signage)	
Answe	er	Finding/Observation
Yes		Fire action notices, assembly point, no smoking, electric hazard, fire door keep shut and running man exit signs are displayed at the main entrance and in the common areas.

Images

N/A

Image: O11







Image: O13



Ref.	Question	Policy Principles
O2	Wayfinding Signage (buildings over 11 metres in height). Are there clear markings for flat and floor recognition provided?	
Answer		Finding/Observation
N/A		



P. Means Of Giving Warning In Case Of Fire

Ref.	Question	Policy Principles
		Folicy Fillicipies
P1	Is a reasonable fire detection and fire alarm system provided in the common areas, where necessary?	
Answer		Finding/Observation
N/A		Smoke detectors are provided to connect to the AOV only
Ref.	Question	Policy Principles
P2	If installed, is the common area AFD adequate for the occupancy and fire risk?	
Answer		Finding/Observation
N/A		
Ref.	Question	Policy Principles
P3	If not installed, are the premises deemed safe without a common area AFD system?	
Answer		Finding/Observation
N/A		
Ref.	Question	Policy Principles
P4	If there is a communal fire detection and fire alarm system, does it extend into the dwellings?	
Answer		Finding/Observation
N/A		
Ref.	Question	Policy Principles
P5	Where appropriate, has a fire alarm zone plan been provided?	
Answer		Finding/Observation
N/A		
Ref.	Question	Policy Principles
P6	Where appropriate, are there adequate arrangements for silencing and resetting an alarm condition?	
Answer		Finding/Observation
N/A		



Ref.	Question	Policy Principle	es	
P7	If applicable, is a separate domestic hard-wired smoke/heat alarm within the flats installed to a suitable standard?			
Answe	r	Finding/Observ	vation .	
Unknown			Flat 25 was accessed to identify it is provided with heat detector in the kitchen and smoke detector in the hallway.	
Action/Recommendation			Priority	Due Date
A category LD3 system should be considered the minimum in all circumstances". However, BS 5839-6:2019 states that "heat detectors should be installed in every kitchen. A smoke detector should be installed in the principal habitable room. Where more than one room might be used as the principal habitable room, a smoke detector should be installed in each of these rooms". It is recommended that each flat is checked to confirm that BS5839-6:2019 Grade D, LD2 detection is fitted.		lled in every e room. room, a mmended	High	24/Sep/2022

Ref.	Question	Policy Principles
P8	If applicable (Sheltered scheme) is the smoke detection within the flats monitored by an alarm receiving centre/on site scheme manager via a telecare system?	
Answer		Finding/Observation
N/A		



Q. Measures To Limit Fire Spread And Development

Ref.	Question	Policy Principles
Q1	Is there adequate levels of compartmentation between floors and between flats and the common escape routes?	
Answer		Finding/Observation
Yes		

Ref.	Question	Policy Principles
Q2	Are hidden voids appropriately enclosed and/or fire-stopped? (consider above suspended ceilings)	
Answer		Finding/Observation
N/A		

Ref.	Question	Policy Principles
Q3	Is there adequately fire protected service risers and/or ducts in common areas, that will restrict the spread of fire and smoke?	
Answer		Finding/Observation
N/A		

Ref.	Question	Policy Principles		
Q4	Is compartmentation maintained in the roof space?			
Answer		Finding/Observation	1	
Unknown		No access to the roo	f space is provided in the co	ommon areas.
Action/Recommendation			Priority	Due Date

Action/Recommendation	Priority	Due Date
Management to confirm that appropriate separation is maintained in the roof	Medium	23/Nov/2022
spaces.		

Ref.	Question	Policy Principles
Q5	Are electrics, including embedded meters, enclosed in fire rated construction?	
Answer	•	Finding/Observation
Yes		The electric meters were enclosed in a separate room which was clear of other items and is provided with FD30S door which was locked shut

Images

Image: Q51





Ref.	Question	Policy Principle	es		
Q6	As far as can reasonably be ascertained, are fire dampers provided as necessary to protect critical means of escape against passage of fire, smoke and products of combustion in the early stages of a fire?				
Answer		Finding/Observ	Finding/Observation		
Unknown		No evidence is	No evidence is kept for inspection on site.		
Action/Recommendation		<u> </u>	Priority	Due Date	
Management should confirm that where and if required fire dampers are as required.		are provided	Medium	23/Nov/2022	

Ref.	Question	Policy Principles
Q7	Is there reasonable limitation of linings to escape routes that might promote fire spread?	
Answer		Finding/Observation
Yes		The surface finishing's appear to be suitable non-flammable materials.

Ref.	Question	Policy Principles
Q8	Are soft furnishings in common areas appropriate to limit fire spread/growth?	
Answer		Finding/Observation
N/A		

Ref.	Question	Policy Principles		
Q9	Does the premises have any external balconies, cladding or materials which may promote external fire spread?			
Answer		Finding/Observation	1	
Yes		The balconies are constructed of galvanised steel although the decks are wooden, and vehicles were parked beneath a balcony. Wooden furniture was also seen stored on one of the balconies.		
		<u> </u>		

Action/Recommendation	Priority	Due Date
Carry out further independent surveys on the balconies to ensure they would not	High	24/Sep/2022
promote fire spread or affect escape from the building.		

Images

Image: Q91





Ref.	Question	Policy Principles	
Q10	Has a note been prepared of the external walls of the building and details of construction materials used? Does the note include and identify the level of risk that the design and materials used?		
Answe	r	Finding/Observation	
Yes		The visiting officer reported that the external surface wall finishing's have been assessed independently and require no further action. See main picture.	
Ref.	Question	Policy Principles	
Q11	Does the External wall note include any mitigating circumstances that may have been taken to reduce the risk?		
Answer		Finding/Observation	
Unkno	wn	See Q10	
Ref.	Question	Policy Principles	
Q12	Has the responsible person reviewed the external wall note on a regular basis and revised it if there have been any significant changes in the external walls.		
Answe	r	Finding/Observation	
Unknown		See Q10	
Ref.	Question	Policy Principles	
Q13	Are all other fire spread/compartmentation issues satisfactory?		
Answer		Finding/Observation	
Yes			

R. Fire Extinguishing Appliances

Ref.	Question	Policy Principles
R1	if required, is there reasonable provision of accessible portable fire extinguishers?	
Answer		Finding/Observation
N/A		Not applicable for this premises.



S. Relevant Automatic Fire Extinguishing Systems

Ref.	Question	Policy Principles
S1	Are there any automatic fire suppressant systems on site?	
Answer		Finding/Observation
No		

Ref.	Question	Policy Principles
S2	Are there any fixed fire fighting mains within the premises?	
Answer		Finding/Observation
No		

Ref.	Question	Policy Principles		
	If any other relevant systems / equipment is installed, state type of system and comment as necessary			
Answer		Finding/Observation		
Yes			provided outside the building nderstood what it is provide	·

Action/Recommendation	Priority	Due Date
Management should clarify and use appropriate signage indicating what the stand pipe is for and who can use it.	Medium	23/Nov/2022

Images

Image: S31





T. Procedures And Arrangements

Ref.	Question	Policy Principles	
T1	Recommended evacuation strategy for this building is		
Answei	•	Finding/Observation	
Stay Put			
Ref.	Question	Policy Principles	
T2	Has a competent person(s) been appointed to assist in undertaking the preventative and protective measures including in house checks?		
Answei	•	Finding/Observation	
Yes		The visiting officer was aware of all fire safety provisions and requirements for the site, and carries out regular inspections.	
Ref.	Question	Policy Principles	
Т3	Are there appropriate documented fire safety arrangements and procedures in place in the event of fire?		
Answei	•	Finding/Observation	
Yes		The information is currently provided on a fire action notice. See 01	
Ref.	Question	Policy Principles	
T4	Are there suitable arrangements for liasion and calling the Fire Service?		
Answer		Finding/Observation	
Yes		Staff, contractors, residents or visitors when the building is occupied will call 999.	
Ref.	Question	Policy Principles	
T5	Are there suitable fire assembly points away from any risk?		
Answei	•	Finding/Observation	
Yes		The fire assembly point is outside in the street and is signed. See O1	
Ref.	Question	Policy Principles	
Т6	Are there adequate procedures in place for the evacuation of disabled people who are likely to be present?		
Answer		Finding/Observation	
Unknov	vn	Unable to confirm at the time of the assessment.	
Ref.	Question	Policy Principles	
T7	Are staff nominated and trained on the use of fire extinguishing appliances?		
Answei		Finding/Observation	
N/A		No staff present.	



Ref.	Question	Policy Principles
Т8	Are staff nominated and trained to assist in evacuation (Where applicable e.g. Offices, supported schemes)?	
Answer		Finding/Observation
N/A		As per T7.

U. Training

Ref.	Question	Policy Principles	
U1	Do staff receive adequate induction and annual refresher fire safety training? (To include fire risks in the premises, fire safety measures in the building, action in the event of fire and on hearing alarm, location and use of fire extinguishers, calling the fire service)	All touchdown points (small offices) staff receive Inductions and annual refreshers on fire safety fire safety. But at all the schemes no permanent staff are present.	
Answer		Finding/Observation	
N/A		As per T7.	
Ref.	Question	Policy Principles	
U2	Are employees nominated to assist in the event of fire given additional training?		
Answer		Finding/Observation	
N/A		As per T7.	



V. Testing And Maintenance

Ref.	Question	Policy Princip	les		
V1	Are all fire safety provisions for the building (AFD,	Alarms- FHG (Alarms- FHG Greenscapes, MITIE		
	Emergency Lighting, sprinklers etc.) routinely tested	E/L- FHG Gree	E/L- FHG Greenscapes, MITIE, Assets Surveyor		
	and maintained? Extingui		MITIE		
			G Greenscapes, Assets	Surveyor	
	Final Exit		cape Routes- Greenscap	es/ Neighbourhoods	
Answe	er	Finding/Obser	vation		
		nswer. rovisions must be tested ards and guides.	in accordance with the		
Action	Recommendation		Priority	Due Date	
The fireman's switch must be tested and maintained in accordance with BS 7671. Automatic opening vents (AOV) are provided on site which must be tested and maintained in accordance with BS EN12101-2. The fixed standpipe should be inspected and checked/flushed as required.		Medium	23/Nov/2022		

Images

Image: V11



W. Records

Ref.	Question	Policy Principles
W1	Is all routine testing and staff training including fire drills suitably recorded and available for inspection?	
Answer		Finding/Observation
N/A		As per T7.

X. Premises Information Box

Ref.	Question	Policy Principles
X1	Is a Premises Information Box located at the premises accessible to the Fire and Rescue Service, secure from unauthorised access and kept up to date?	Log book is kept on SharePoint with proposed specific QR code access.
Answei	•	Finding/Observation
N/A		None present and not required.



Y. Engagement With Residents

Ref.	Question	Policy Principles	
Y1	Has all Fire Safety information & procedures been disseminated to the residents?		
Answer		Finding/Observation	
No		It is important to ensure residents are kept informed	

Z. Any Other Information

Ref.	Question	Policy Principles
Z1	Are all issues deemed satisfactory? [1]	
Answer		Finding/Observation
Yes		
Ref.	Question	Policy Principles
Z2 Are all issues deemed satisfactory?		
Answer		Finding/Observation
Yes		



ZAAR. Assessment Risk Ratings

Ref.	Question	Policy Principles
ZAAR1	Likelihood of Fire Low: Unusually low likelihood of fire as a result of negligible potential sources of ignition. Medium: Normal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings). High: Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire	
Answer		Finding/Observation
Medium		

Ref.	Question	Policy Principles
ZAAR2	Potential Consequences of Fire Slight harm: Outbreak of fire unlikely to result in serious injury or death of any occupant. Moderate harmful: Outbreak of fire could foreseeably result in injury (including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities. Extreme harm: Significant potential for serious injury or death of one or more occupants likely to involve multiple fatalities	
Answer		Finding/Observation
Moderate Harm		

Ref.	Question	Policy Principles
ZAAR3	Premises Risk Rating	
	Trivial: No action is required and no detailed records	
	need be kept	
	Tolerable: No major additional controls required.	
	However, there might be a need for improvements that	
	involve minor or	
	limited cost.	
	Moderate: It is essential that efforts are made to	
	reduce the risk. Risk reduction measures should be	
	implemented within a	
	defined time period. Where moderate risk is	
	associated with consequences that constitute	
	extreme harm, further	
	assessment might be required to establish more	
	precisely the likelihood of harm as a basis for	
	determining the	
	priority for improved control measures.	
	Substantial: Considerable resources might have to be	
	allocated to reduce the risk. If the building is	
	unoccupied, it should not	
	be occupied until the risk has been reduced. If the	
	building is occupied, urgent action should be taken.	
	Intolerable: Building (or relevant area) should not be	
	occupied until the risk is reduced	
Answer		Finding/Observation
Moderat	e	

Ref.	Question	Policy Principles
ZAAR4	On satisfactory completion of all remedial works the risk rating of this building may be reduced to:	
Answer		Finding/Observation
Tolerable		

Risk Rating



The following simple risk level estimator is based on a more general health and safety risk level estimator of the type contained in BS 8800:

Libelihaad of five	Potential consequences of fire		
Likelihood of fire	Slight Harm	Moderate Harm	Extreme Harm
Low	Trivial	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at these premises is:

Medium

In this context, a definition of the above terms is as follows:

Low: Unusually low likelihood of fire as a result of negligible potential sources of ignition.

Medium: Normal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).

High: Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire

Taking into account the nature of the building and occupants, as well as the fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the consequences for life safety in the event of fire would be:

Moderate Harm

In this context, a definition of the above terms is as follows:

Slight harm: Outbreak of fire unlikely to result in serious injury or death of any occupant.

Moderate harmful: Outbreak of fire could foreseeably result in injury (including serious injury) of one or more occupants, but it is unlikely to involve multiple fatali-ties.

Extreme harm: Significant potential for serious injury or death of one or more occupants likely to involve multiple fatalities.

Accordingly, it is considered that the risk to life from fire at these premises is:

Moderate

A suitable risk-based control plan should involve effort and urgency that is proportional to risk. The following risk-based control plan is based on one advocated by BS 8800 for general health and safety risks:

Risk Level	Action and time table
Trivial	No action is required and no detailed records need be kept.
Tolerable	No major additional controls required. However, there might be a need for improvements that involve minor or limited cost.
Moderate	It is essential that efforts are made to reduce the risk. Risk reduction measures should be implemented within a defined time period. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measures.
Substantial	Considerable resources might have to be allocated to reduce the risk. If the building is unoccupied, it should not be occupied until the risk has been reduced. If the building is occupied, urgent action should be taken.
Intolerable	Building (or relevant area) should not be occupied until the risk is reduced.

(Note that, although the purpose of this section is to place the risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly.)





Life Safety Fire Risk Assessment Certificate of Conformity

This certificate is issued by the organization named in Part 1 of the schedule in respect of fire risk assessment provided for the person(s) or organization named in Part 2 of the schedule at the premises and / or part of the premises identified in Part 3 of the schedule.

Schedule:

Part 1a	Name & Address of Certified Organisation:
	Pennington Choices, Broofield House, Grimsditch Lane, WA4 4EA
Part 1b	BAFE registration number of issuing Certified Organization:
	102119
Part 1c	SSAIB 3rd Party Certificate Number:
	CHES077
Part 2	Name of Client:
	CEO Futures
Part 3a	Address of premises for which the fire risk assessment was carried out:
	De Senlis, Jerome Court Northampton Northampton NN3 5GA
Part 3b	Part or parts of the premises to which the fire risk assessment applies:
	Common Parts only (not dwellings, where applicable)
Part 4	Brief description of the scope and purpose of the fire risk assessment:
	Life Safety (as per agreed Specification)
Part 5	Effective date of the fire risk assessment:
	01/08/2022
Part 6	Recommended date for reassessment of the premises:
	01/08/2023
Part 7	Unique reference number of this certificate:
	109266
	Recommended date for reassessment of the premises: 01/08/2023 Unique reference number of this certificate:

Signed for and on behalf of the issuing Certificated Organization:

James Hutton

Dated: 8/25/2022

Appendix 1. Action Details

Ref.	Category	Priority	Comments	Recommendation	Quantity	To Be Completed By	Photo Ref.
C2	ARSON	No Timescale	Waste and recycling are stored inside a dedicated bin store	It is recommended that a sign is displayed outside the bin store for the emergency services			C21
F1	LIGHTNING	No Timescale	No lightning protection system was identified during the assessment.	Recommend management undertake a risk assessment of the building to determine if lightning protection is required			
H1	HAZARDS INTRODUCED BY CONTRACTORS	Medium	No policy available to determine if satisfactory control over works are carried out in the building for in-house contractors and outside contractors (e.g. hot work permits).	Signage should be provided at the main entrance indicating safe practices to be carried out by all visiting contractors. A documented procedure is recommended for ensuring all contractors are controlled on site and only operate within approved industry standards. This should include a permit to work and a hot work permit procedure where appropriate. All contractors should be advised of the emergency procedures and hazardous areas.		23/11/2022	
P7	MEANS OF GIVING WARNING IN CASE OF FIRE	High	Flat 25 was accessed to identify it is provided with heat detector in the kitchen and smoke detector in the hallway.	A category LD3 system should be considered the minimum in all circumstances". However, BS 5839-6:2019 states that "heat detectors should be installed in every kitchen. A smoke detector should be installed in the principal habitable room. Where more than one room might be used as the principal habitable room, a smoke detector should be installed in each of these rooms". It is recommended that each flat is checked to confirm that BS5839-6:2019 Grade D, LD2 detection is fitted.		24/09/2022	
Q4	MEASURES TO LIMIT FIRE SPREAD AND DEVELOPMENT	Medium	No access to the roof space is provided in the common areas.	Management to confirm that appropriate separation is maintained in the roof spaces.		23/11/2022	!
Q6	MEASURES TO LIMIT FIRE SPREAD AND DEVELOPMENT	Medium	No evidence is kept for inspection on site.	Management should confirm that where and if required fire dampers are provided as required.		23/11/2022	!
Q9	MEASURES TO LIMIT FIRE SPREAD AND DEVELOPMENT	High	The balconies are constructed of galvanised steel although the decks are wooden, and vehicles were parked beneath a balcony. Wooden furniture was also seen stored on one of the balconies.	Carry out further independent surveys on the balconies to ensure they would not promote fire spread or affect escape from the building.		24/09/2022	Q91

Ref.	Category	Priority	Comments	Recommendation	Quantity	To Be Completed By	Photo Ref.
Q10	MEASURES TO LIMIT FIRE SPREAD AND DEVELOPMENT	No Timescale	The visiting officer reported that the external surface wall finishing's have been assessed independantly and require no further action. See main picture.	As the external wall surface finishing's extend to the side of a single access/exit door it is recommended that the current risk assessment of external wall surface finishing's is re addressed to take that into account if this has not already been done			
S3	RELEVANT AUTOMATIC FIRE EXTINGUISHING SYSTEMS	Medium	A fixed standpipe is provided outside the building which is also locked and it is not understood what it is provided for and who can use it.	Management should clarify and use appropriate signage indicating what the stand pipe is for and who can use it.		23/11/2022	S31
T6	PROCEDURES AND ARRANGEMENTS	No Timescale	Unable to confirm at the time of the assessment.	Person Centered Fire Risk Assessments should be carried out on all tenants in general needs property, when required, and should be reviewed on an annual basis.			
V1	TESTING AND MAINTENANCE	Medium	See principle answer. All fire safety provisions must be tested in accordance with the relevant standards and guides.	The fireman's switch must be tested and maintained in accordance with BS 7671. Automatic opening vents (AOV) are provided on site which must be tested and maintained in accordance with BS EN12101-2. The fixed standpipe should be inspected and checked/flushed as required.		23/11/2022	V11
Y1	ENGAGEMENT WITH RESIDENTS	No Timescale	It is important to ensure residents are kept informed	Safety information should be regularly updated to residents using different formats including letters, social media and posters etc			